The disintegration of concrete containing sulphate-contaminated aggregates*

M. A. Samarai

CORRIGENDA

Figures 5 and 6: From the captions, delete “, as part of the sand,”

Figure 5: On the Figure itself, the SO_3 contents should read, clockwise from the top: 9.26%, 7.36%, 6.41%, 5.46%, 4.50%, 2.60%, 3.55%. The corrected Figure is shown below.

Conclusions, page 141: In line 5 of conclusion 1: *for 4.5% read 0.6%*
 In line 6 of conclusion 1: *for 6.0% read 0.7%*
 In line 10 of conclusion 2: *for 15.2% read 5.2%*

Figure 5: Effect of SO_3 content upon the expansion of mortar prisms made with cement A.

*Pages 130 to 142 of MCR 96