Editorial

Tai-Tien Wang MEng, PhD

Professor, Institute of Mineral Resources Engineering, National Taipei University of Technology, Taiwan, ROC

Since the launch of the London Underground transportation system in 1963, the utilisation of underground space has always been considered the main solution to solving the shortage of land space under the pressures of rapid urbanisation. In addition to issues regarding energy supply in the 21st century, there are increasing concerns about global climate change. The utilisation of underground space is regarded as one of the best options for sustainable development of society. In spite of the extremely expensive cost and high risks during construction, tunnels and underground structures are robust and durable and will require low maintenance costs. Because of this, over the past century it has always been considered the main approach to solving problems in the field of public construction.

Is the construction tunnel really robust and durable? If it is, will that proposition conflict with this themed issue's subject of tunnel failure? Have shortcomings in the constructed tunnels been ignored during the design and construction process just because defects have existed in the theory of modernised tunnel mechanics or the construction method could not meet the requirements of environment-related sustainable development? What remedial measures should be taken to solve the problems foreseen in tunnel planning and construction? How should a competent authority responsible for public construction and infrastructure manage the large number of tunnels that are being constructed and put into service? These issues are addressed by the six papers in this two-part themed issue. The second part of this themed issue will be published in November 2014. All papers are available ahead of print on the ICE Virtual Library.

In nature the tunnel is different from the historical building stock. Normally, the design life of modern civil work is not expected to exceed 100 years. What will the tunnel look like a century from now? In the first paper, Chiu *et al.* (2014) select as a case study the first masonry tunnel constructed in Taiwan in the 1880s, through which the anomalies of masonry lining are reported. Conclusions as to the causes of anomalies are also proposed.

In the second paper the focus is on the study of ground surface settlement and neighbouring damage problems along the construction route of metropolitan tunnels in Dublin, Ireland (Gillarduzzi, 2014). An engineering-geological ground model was developed through a comprehensive procedure including the collection and integration of data from conventional

investigation and from historical building performance. A review of groundwater monitoring and tunnel construction records has effectively clarified the causes for the varying settlement in different sections along these tunnels.

The final paper in this August issue (Coggan and Yelland, 2014) considers an undersea tunnel constructed 25 m below the seabed using the drilling and blasting method. To mitigate against water ingress, systematic probe drilling was used to provide geological forecasts ahead of the excavation face. With the help of Q-method geological assessment and engineering judgement, ground grouting was used ahead of the advancing face in geologically weak sections.

The lining anomalies of in-service tunnels impact structural safety, service quality and the subsequent service life of tunnels. Lee and Wang (2014), in the first paper in the November issue, propose an innovative procedure to characterise and digitize the spatial distribution of lining cracks obtained through tunnel surface image identification. Furthermore, the results are employed to establish correlation with the causes of anomalies so that it is possible to effectively diagnose eight possible causes contributing to lining anomalies.

Palazzo (2014), in the second paper in the November issue, provides a very interesting introduction to mitigating tunnel construction risks through the development of forensic engineering and the efforts of the forensic engineer. In this paper, the circumstances of a hydraulic tunnel being erected in Italy at the beginning of the 1990s are investigated. The project was terminated when a pressure aquifer was discovered at the tunnel entrance. The paper provides a well-based examination of the structure of construction contracts in that era, the legal ramifications between the client and the contractor during the contract execution and dispute process, and amendment of subsequent tunnel forensic engineering practice.

The final paper in the November issue (Pang, 2014) considers the mitigation of the impact of tunnel work on the geotechnical environment with an engineering management aspect. It takes Hong Kong, which is a mountainous, narrow, densely populated and rapidly developing area, as an example. In Hong Kong several catastrophic slope hazards in the 1970s pushed the development of a modernised geotechnical engineering specification and relevant government organizational structure. The paper

describes the efforts of the Hong Kong government in gradually promoting this system of tunnel construction, while discussing, as a practical application, the example of the Harbour Area Treatment Scheme (Hats) programme. Hong Kong as a case study offers a pioneering example for engineering management in preventing tunnel damage.

I hope that these papers will provide new ideas and usable information on tunnel damage, and would be pleased to receive comments and discussion of this two-part issue and the six papers.

REFERENCES

- Chiu YC, Wang TT and Huang TH (2014) Investigating continual damage of a nineteenth century masonry tunnel. *Proceedings of the Institution of Civil Engineers – Forensic Engineering* **167(3)**: 109–118, <http://dx.doi.org/10.1680/feng.13.00030>.
- Coggan J and Yelland S (2014) Negotiation of poor ground in an undersea tunnel. *Proceedings of the Institution of Civil Engineers – Forensic Engineering* **167(3)**: 143–150, <http://dx.doi.org/10.1680/feng.13.00027>.
- Gillarduzzi A (2014) Investigating property damage along Dublin Port Tunnel alignment. *Proceedings of the Institution of Civil Engineers – Forensic Engineering* **167(3)**: 119–142, <http://dx.doi.org/10.1680/feng.13.00024>.
- Lee CH and Wang TT (2014) Diagnosing causes of lining cracks in mountain tunnels. *Proceedings of the Institution of Civil Engineers – Forensic Engineering*, <http://dx.doi.org/10.1680/feng.13.00029>.
- Palazzo S (2014) Tunnel excavation failures and unforeseen ground conditions. *Proceedings of the Institution of Civil Engineers – Forensic Engineering*, <http://dx.doi.org/10.1680/feng.13.00026>.
- Pang PL (2014) Geotechnical control of tunnel works in Hong Kong. *Proceedings of the Institution of Civil Engineers – Forensic Engineering*, <http://dx.doi.org/10.1680/feng.13.00025>.